



A new wavelength calibration has been performed on my spectrometer, but the coefficients are still in the old settings.

Please follow the procedure described below to activate the new calibration settings.

- Connect the spectrometer to the computer using the USB2 cable.
- Start Avasoftware.
- 1) Go to "settings". 
- 2) Go to "Wavelength Coefficients".
- 3) Click on "restore factory settings" button.

The new coefficients are now loaded into the EEPROM.



1) Settings

2) Wavelength Coefficients

3) Restore Factory Settings